7100




Fig. 1 (Prior Art)







Fig. 2 (Prior Art)







• • •




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10

Output Ports

	Output Port 0	Output Port 1	Output Port 2	Output Port 3
Input Port 0	Insertion Loss	Insertion Loss	•	
	Value A	Value B		
Input Port 1	Insertion Loss	Insertion Loss		
	Value C	Value D		
Input Port 2	Insertion Loss	Insertion Loss		
	Value E	Value F		
Input Port 3	•••	• •		
	•	•		

Fig. 11A

Output Ports

	Output Port 3					
	Output Port 2	• • •	• • •	• • •	•	•
	Output Port 1	Time Value B	Time Value D	Time Value F	•	•
	Output Port 0	Time Value A	Time Value C	Time Value E	•	•
,		Input Port 0	Input Port 1	Input Port 2	Input Port 3	
		Input	Ports	1102	<u> </u>	•

Fig. 11B